


QUICK-CHANGE SOLID DRIVE TAPPING CHUCKS**PORTAMACHOS DE CAMBIO RÁPIDO****GEWINDESCHNEID-SCHNELLWECHSELFUTTER FÜR MASCHINEN MIT SPINDELSYNCHRONISATION****019 14 53 ...**

For synchronized feed control machines.
Exclusivo para máquinas con control de roscado rígido.
Für Maschinen mit Spindelsynchronisation.



K	Cap.	D1	L	D	COD.	Availability Disponibilidad Verfügbarkeit
40	M3-M12 (M16)*	19	61	32	019 14 53 02 02	■
63	M3-M12 (M16)*	19	67	32	019 14 53 04 02	■
63	M8-M20 (M30)*	31	87	50	019 14 53 04 03	■
100	M3-M12 (M16)*	19	70	32	019 14 53 06 02	■
100	M8-M20 (M30)*	31	90	50	019 14 53 06 03	■
100	M14-M33 (M48)*	48	116	72	019 14 53 06 04	■

* With 002 22 Adapters.

- Coolant tube to be ordered separately.

* Con adaptadores 002 22

- El tubo de refrigerante se suministra bajo demanda expresa.

*Mit Adaptern 002 22

- Kühlmittelrohre bitte separat bestellen.

RELATIONATED ELEMENTS
ELEMENTOS RELACIONADOS
VERWANDTE ARTIKEL

Page: 250



002 20 00 ...



002 21 ...



002 22 ...