

Technical drawing of a mechanical assembly. The drawing shows a cross-section of a component with various dimensions labeled. The dimensions are: l_1 , l_2 , h_1 , d_1 , b_1 , b_2 , h_3 , h_0 , and $0,5$, $0,1$. The drawing includes a detailed view of a threaded section on the right side.

prawa/right

Krótki uchwyt wiertarski/ Integraf taper drill chucks

łącznie z uchwytem/ with drill chuck

bez uchwytu/without drill chuck